

Gambaran Fasilitas Sanitasi Wisata Telaga Ngebel di Kecamatan Ngebel Kabupaten Ponorogo Tahun 2022

Novika Dwi Cahyanti*, Sarjito Eko Windarso**, Mohamad Mirza Fauzie** Jurusan Kesehatan Lingkungan Poltekkes Kemenkes Yogyakarta
Jl. Tatabumi No. 3, Banyuraden, Gamping, Sleman,
Yogyakarta 55293 Email: novikacahyanti00@gmail.com

INTISARI

Pariwisata merupakan sektor ekonomi yang cukup penting di Indonesia dan terus mengalami peningkatan kunjungan wisatawan mancanegara setiap tahunnya. Berdirinya Pariwisata diakui dapat menggerakkan ekonomi dan memberdayakan masyarakat. Pemerintah Indonesia telah mengakui potensi kemajuan ekonomi yang dapat dilakukan oleh industri Pariwisata yang Tangguh. Menurut Undang-Undang Republik Indonesia tahun 2009 Industri wisata merupakan suatu upaya pariwisata yang saling terkait dalam rangka menghasilkan barang atau jasa bagi pemenuhan kebutuhan wisatawan dalam penyelenggaraan pariwisata. Fasilitas sarana sanitasi tersebut diantaranya :keberadaan toilet umum, sarana penyediaan air bersih, tempat sampah yang memadai dan sarana pembuangan air limbah (SPAL). Fasilitas sarana sanitasi di Pariwisata merupakan prasarana untuk menunjang kenyamanan pada suatu objek wisata. Semakin baik fasilitas sarana sanitasinya maka semakin tinggi tingkat kenyamanan wisatawan yang berkunjung. Fasilitas sanitasi yang tidak terjaga kebersihannya akan memberikan dampak buruk pada pengunjung seperti, penularan berbagai penyakit infeksi misalnya diare, kolera, typhoid, penyakit kulit, dan lain sebagainya. Tujuan dari dilakukannya penelitian ini adalah untuk mengetahui gambaran kondisi lingkungan dan kondisi fasilitas sarana sanitasi di tempat Pariwisata Telaga Ngebel Kabupaten Ponorogo tahun 2022. Penelitian ini merupakan jenis penelitian survey deskriptif yang dilakukan dengan metode observasi dengan pengisian *checklist* yang mengacu pada Permenkes No. 14 tahun 2021 tentang Standar Kegiatan Usaha dan Produk pada Penyelenggaraan Perizinan Berusaha Berbasis Risiko Sektor Kesehatan dan wawancara dengan pihak-pihak terkait. Berdasarkan *checklist* yang digunakan sebagai acuan penelitian pariwisata yang termasuk kedalam kategori laik sehat yaitu pariwisata yang jika di nilai dengan *checklist* tersebut mendapat skor >70 poin. Hasil penelitian yang dilakukan dengan formulir *checklist* tersebut menunjukkan bahwa kondisi fasilitas sarana sanitasi di Parwisata Telaga Ngebel dapat di kategorikan ke dalam "laik sehat" karena setelah dilakukan penilaian mendapat poin 38 poin dari poin keseluruhan 50 poin dan jika dihitung kembali dengan rumus mendapatkan nilai 76 poin. Fasilitas sarana sanitasi di Pariwisata Telaga Ngebel secara penilaian memenuhi syarat, tetapi ada beberapa hal yang perlu diperbaiki untuk meningkatkan mutu sarana sanitasi tersebut diantaranya kamar mandi sebaiknya dalam penggunaannya terpisah laki-laki dan perempuan dan TPS yang sebaiknya di bangun bak sebagai penampung sementara. Fasilitas sarana sanitasi di Pariwisata Telaga Ngebel yang "laik sehat" akan meningkatkan kepuasan pengunjung.

Kata Kunci :Fasilitas Sanitasi Pariwisata.

Overview Of The Ngebel Lake Tourism Sanitation Facility in Ngebel Sub-district, Ponorogo Regency in 2022

Novika Dwi Cahyanti*, Sarjito Eko Windarso**, Mohamad Mirza Fauzie** Department of Environmental Health Poltekkes Ministry of Health Yogyakarta Jl. Tatabumi No. 3, Banyuraden, Gamping, Sleman, Yogyakarta 55293 Email: novikacahyanti00@gmail.com

ABSTRACT

Tourism is an important economic sector in Indonesia and continues to experience an increase in foreign tourist arrivals every year. The establishment of Tourism is recognized as being able to drive the economy and empower the community. The Government of Indonesia has recognized the potential for economic progress that the Resilient Tourism industry can make. According to the 2009 Law of the Republic of Indonesia, the tourism industry is an interrelated tourism effort in the context of producing goods or services to meet the needs of tourists in the implementation of tourism. These sanitation facilities include: the presence of public toilets, clean water supply facilities, adequate trash cans and waste water disposal facilities (SPAL). Sanitation facilities in tourism are infrastructure to support comfort in a tourist attraction. The better the sanitation facilities, the higher the comfort level of visiting tourists. Sanitation facilities that are not kept clean will have a negative impact on visitors, such as the transmission of various infectious diseases such as diarrhea, cholera, typhoid, skin diseases, and so on. The purpose of this research is to describe the environmental conditions and the condition of the sanitation facilities at the lake Tourism site, Ponorogo Regency in 2022. This research is a type of descriptive survey research conducted using the observation method by filling out a checklist that refers to the Minister of Health Regulation No. 14 of 2021 concerning Standards for Business Activities and Products in the Implementation of Risk-Based Business Licensing in the Health Sector and interviews with related parties. Based on the checklist that is used as a reference for tourism research, which is included in the healthy-worth category, namely tourism, which if judged by the checklist, gets a score of >70 points. The results of the research conducted using the checklist form indicate that the condition of the sanitation facilities at Ponorogo lake tourism can be categorized into "fit for health" because after the assessment, it gets 38 points out of a total of 50 points and if it is calculated again with the formula, it gets a score of 76 points. Sanitation facilities at Telaga Ngebel Tourism are assessed to meet the requirements, but there are several things that need to be improved to improve the quality of these sanitation facilities, including bathrooms should be used separately for men and women and TPS which should be built as temporary reservoirs. Sanitation facilities at Ngebel lake Tourism that are "fit for health" will increase visitor satisfaction.

Keywords: Tourism sanitation facilities.