

Description Of Sanitation In Extraordinary School Kasih Ibu Brosot Kulon

Progo Year 2022

Anggita Dewi Kusumastuti*, Sri Puji Ganefeti**, Heru Subaris Kasjono**
Departemen Of Environmental Health Poltekkes Kemenkes Yogyakarta
Jl. Tatat Bumi No. 3, Banyuraden, Gamping, Sleman, Yogyakarta 55293
Email : anggitadewi381@gmail.com

ABSTRACT

Based on the results of a preliminary survey at the Kasih Ibu Special School, there were various problems with the condition of sanitation facilities including toilets, waste water sewers (SPAL), trash cans.

This research was conducted with the aim of knowing the condition of the existing sanitation facilities at the Kasih Ibu Special School. This type of research is a survey with a descriptive purpose. The results of this study found that sanitation

facilities in the clean water aspect of the 3 variables studied all met the requirements. The toilet aspect of the 8 variables studied, 4 variables did not meet the requirements, including the separation of toilets between men and women, soap and trash cans available, adequate ventilation and lighting, no mosquito larvae. Aspects of Wastewater Sewerage from the 6 variables studied, 1 variable did not meet the requirements, including wastewater flowing smoothly. Aspects of the trash bin of the 3 variables studied, 2 variables that do not meet the requirements include a covered trash can, the distance between TPS and classrooms is at least 10 meters.

The conclusion of this study is that the condition of the sanitation facilities at the Kasih Ibu Special School got a score of 13 eligible variables with a percentage (65%) meaning "Not Healthy Eligible" where the healthy acceptable standard if the eligible variable has a value of 70%.

Keywords: Sanitation, Condition of Sanitation Facilities, Schools, Special Schools

Gambaran Sanitasi Di Sekolah Luar Biasa Kasih Ibu Brosot Kulon Progo

Tahun 2022

Anggita Dewi Kusumastuti*, Sri Puji Ganefeti**, Heru Subaris Kasjono**
Jurusan Kesehatan Lingkungan Poltekkes Kemenkes Yogyakarta
Jl. Tatat Bumi No. 3, Banyuraden, Gamping, Sleman, Yogyakarta 55293
Email : anggitadewi381@gmail.com

INTISARI

Berdasarkan hasil survey pendahuluan di Sekolah Luar Biasa Kasih Ibu terdapat berbagai permasalahan kondisi sarana sanitasi meliputi toilet, saluran pembuangan air limbah (SPAL), tempat sampah.

Penelitian ini dilakukan dengan tujuan mengetahui kondisi sarana sanitasi yang ada di Sekolah Luar Biasa Kasih Ibu. Jenis penelitian ini adalah survey dengan tujuan deskriptif. Hasil penelitian ini didapatkan bahwa sarana sanitasi pada aspek air bersih dari 3 variabel yang diteliti semua variabel memenuhi syarat. Aspek toilet dari 8 variabel yang diteliti, 4 variabel tidak memenuhi syarat antara lain adanya pemisahan toilet antara laki-laki dan perempuan, tersedia sabun dan tempat sampah, ada ventilasi dan penerangan yang cukup, tidak ada jentik nyamuk. Aspek Saluran Pembuangan Air Limbah dari 6 variabel yang diteliti 1 variabel tidak memenuhi syarat antara lain air limbah mengalir dengan lancar. Aspek tempat sampah dari 3 variabel yang diteliti, 2 variabel tidak memenuhi syarat antara lain tempat sampah berpenutup, jarak TPS dan ruang kelas minimal 10 meter.

Kesimpulan pada penelitian ini adalah kondisi sarana sanitasi di Sekolah Luar Biasa Kasih Ibu memperoleh nilai 13 variabel memenuhi syarat dengan presentase (65%) artinya “Tidak Laik Sehat” dimana standar laik sehat apabila variabel yang memenuhi syarat memiliki nilai $\geq 70\%$.

Kata kunci : Sanitasi, Kondisi Sarana Sanitasi, Sekolah, Sekolah Luar Biasa