

Kajian Sanitasi Sarana dan Prasarana Kolam Renang Clereng di Kecamatan Pengasih Kabupaten Kulon Progo Tahun 2019

Nur Syahidah Rahmawati¹, Abdul Hadi Kadarusno², Herman Santjoko³
¹⁻³Jurusan Kesehatan Lingkungan Poltekkes Kemenkes Yogyakarta
Jalan Tata Bumi Nomor 3 Banyuraden, Gamping, Sleman, Yogyakarta, 55293
Email : nursyahidahrahmawati1@gmail.com

INTISARI

Kolam renang adalah salah satu tempat-tempat umum yang memungkinkan terjadi penyebaran penyakit jika memiliki kondisi sanitasi yang buruk. Berdasarkan survei diketahui bahwa, keadaan sanitasi di Kolam Renang Clereng masih kurang terutama pada kebersihan di lingkungan kolam.

Penelitian ini bertujuan untuk mengetahui keadaan sanitasi sarana dan prasarana Kolam Renang Clereng yaitu untuk mengetahui keadaan kesehatan lingkungan dan bangunan, keadaan kamar atau ruang yang ada di lingkungan, keadaan fasilitas sanitasi dan keadaan kesehatan kualitas air kolam renang.

Jenis penelitian yang digunakan adalah penelitian survei dengan analisis deskriptif. Lokasi penelitian di Pedukuhan Mrunggi, Desa Sendangsari, Kecamatan Pengasih, Kabupaten Kulon Progo dengan objek penelitian berupa sarana dan prasarana yang ada di kolam renang Clereng.

Hasil penelitian ini menyebutkan bahwa keadaan kesehatan lingkungan dan bangunan (64,4%), keadaan kamar atau ruang (50%), keadaan kesehatan kualitas air (56,5%) yang artinya Tidak Laik Sehat serta keadaan fasilitas sanitasi (86,7%) yang artinya Laik Sehat. Hasil penilaian peneliti secara keseluruhan dari sanitasi sarana dan prasarana (69,7%) yang menyatakan bahwa sanitasi di Kolam Renang Clereng masuk dalam kategori Tidak Laik Sehat.

Kata Kunci : Sanitasi, Tempat-Tempat Umum, Sarana Dan Prasarana, Kolam Renang.

ABSTRACT

Sanitation Study of Clereng Swimming Pool Facilities and Infrastructures in Pengasih, Kulon Progo Regency 2019

Nur Syahidah Rahmawati¹, Abdul Hadi Kadarusno², Herman Santjoko³
¹⁻³Jurusan Kesehatan Lingkungan Poltekkes Kemenkes Yogyakarta
Jalan Tata Bumi Nomor 3 Banyuraden, Gamping, Sleman, Yogyakarta, 55293
Email : nursyahidahrahmawati1@gmail.com

Swimming pool is one of public places that enable to happen spread of disease it has bad sanitation. Based on the survey, it is known that the state of sanitation at the Clereng Swimming Pool is deficient, mainly at the cleanliness around the pool.

This research is aimed to know the state of sanitation of the Clereng Swimming Pool's infrastructures. Which means to know the buildings and environmental health, conditions of the rooms around, states of the sanitation facility, and the condition of the quality of the swimming pool's water.

Type of the research that is used is a survey research with analitic description. Location of the research is at Mrunggi Hamlet, Sendangsari Village, Pengasih Sub-district, Kulon Progo District as an object of the research is the infrastructures which are at the Clereng Swimming pool.

The result of this research shows that the buildings and environmental health (64,4%), conditions of the rooms (50%), the condition of the quality of the water (56,5%) which means not good, and the states of the sanitation facility (86,7%) which means good. Overall the result of the researcher's rating from the infrastructure of the sanitation (69,7%) which means that the sanitation of the Clereng Swimming Pool falls into the not decent and healthy category.

Keywords : Sanitations, Public Places, Infrastructures, Swimming Pool.