

**GAMBARAN KONDISI TOILET UMUM YANG DIKELOLA DINAS
PARIWISATA DAN PEMILIK WARUNG MAKAN DI PANTAI
GOA CEMARA KABUPATEN BANTUL DAERAH
ISTIMEWA YOGYAKARTA**

Nurul Fitriyana *, Yamtana, Siti Hani Istiqomah
Jurusan Kesehatan Lingkungan Poltekkes Kemenkes Yogyakarta
Jl. Tata Bumi No.3 Banyuraden, Gamping, Sleman, Yogyakarta, 55293
Email: nurulfitriyana2008@gmail.com

INTISARI

Tempat umum memiliki potensi sebagai tempat terjadinya penularan penyakit, pencemaran lingkungan atau gangguan kesehatan. Kualitas toilet disebuah obyek wisata akan menambah syarat sanitasi lingkungkan pariwisata. Kondisi lingkungan wisata pantai di Bantul memiliki sanitasi lingkungan yang kurang sehat. Hal ini dibuktikan dengan kondisi toilet umum di Pantai Goa Cemara yang tidak terawat, tidak terdapat pemisahan antara pria dan wanita, dan masih banyak toilet yang belum menyediakan sabun. Persyaratan toilet yang baik yaitu dengan dilengkapi sabun dan juga tempat sampah kedap air.

Berdasarkan studi pendahuluan sebelumnya kondisi toilet umum di Pantai Goa Cemara memiliki nilai 0 pada syarat toilet yaitu terpisah antara pria dan wanita serta kebersihan toilet yang masih kurang dijaga sehingga peneliti ingin mengetahui lebih detail kondisi sanitasi toilet yang tersedia di Pantai Goa Cemara.

Penelitian ini dilakukan dengan tujuan untuk mengetahui kondisi toilet umum yang dikelola oleh Dinas Pariwisata dan Pemilik Warung Makan di Pantai Goa Cemara Kabupaten Bantul.

Metode dalam penelitian ini yaitu menggunakan jenis penelitian survei deskriptif. Penelitian ini berlokasi di Pantai Goa Cemara, Kabupaten Bantul, Daerah Istimewa Yogyakarta. Obyek penelitian ini adalah sarana sanitasi toilet umum di Pantai Goa Cemara. Hasil penelitiannya adalah toilet umum yang dikelola oleh Dinas Pariwisata di Pantai Goa Cemara didapatkan 57% yang dapat dikategorikan laik sehat, dan 43% yang dapat dikategorikan tidak laik sehat. Toilet umum yang dikelola oleh Pemilik Warung Makan di Pantai Goa Cemara didapatkan 88% yang dapat dikategorikan laik sehat, dan 12% yang dapat dikategorikan tidak laik sehat.

Kesimpulan dari penelitian ini adalah kondisi kontruksi bangunan, dan fasilitas sanitasi toilet umum yang dikelola oleh Dinas Pariwisata didapatkan nilai masing-masing 68,8%, dan 84,9% sedangkan kondisi kontruksi bangunan, dan fasilitas sanitasi toilet umum yang dikelola oleh Pemilik Warung Makan didapatkan nilai masing-masing 76%, dan 91,7%.

Kata Kunci: kondisi sanitasi, toilet umum, tempat wisata, pantai.

**GAMBARAN KONDISI TOILET UMUM YANG DIKELOLA DINAS
PARIWISATA DAN PEMILIK WARUNG MAKAN DI PANTAI
GOA CEMARA KABUPATEN BANTUL DAERAH
ISTIMEWA YOGYAKARTA**

Nurul Fitriyana*, Yamtana, Siti Hani Istiqomah
Jurusan Kesehatan Lingkungan Poltekkes Kemenkes Yogyakarta
Jl. Tata Bumi No.3 Banyuraden, Gamping, Sleman, Yogyakarta, 55293
Email: nurulfitriyana2008@gmail.com

ABSTRACT

Public places have the potential as a place for disease transmission, environmental pollution or health problems. The quality of toilets in a tourist attraction will add to the sanitation requirements for the tourism environment. The condition of the coastal tourism environment in Bantul has an unhealthy environmental sanitation. This is evidenced by the condition of the public toilets at Goa Cemara Beach which are not maintained, there is no separation between men and women, and there are still many toilets that do not provide soap. The requirements for a good toilet are equipped with soap and also a watertight trash can.

Based on previous preliminary studies, the condition of public toilets at Goa Cemara Beach has a value of 0 on the toilet requirements, namely separate between men and women and the cleanliness of the toilets is still poorly maintained, so the researcher wants to know in more detail the sanitary conditions of the toilets available at Goa Cemara Beach.

This research was conducted with the aim of knowing the condition of public toilets managed by the Tourism Office and Food Stall Owners at Goa Cemara Beach, Bantul Regency.

The method in this research is to use a descriptive survey research type. This research is located at Goa Cemara Beach, Bantul Regency, Yogyakarta Special Region. The object of this research is the sanitation facilities for public toilets at Goa Cemara Beach. The result of the research is that the public toilets managed by the Tourism Office at Goa Cemara Beach found 57% of which can be categorized as fit for health, and 43% which can be categorized as unfit for health. Public toilets managed by the owners of the food stalls at Goa Cemara Beach found 88% of which could be categorized as healthy, and 12% which could be categorized as unhealthy.

The conclusion of this research is the conditions of building construction, and public toilet sanitation facilities managed by the Tourism Office, each obtained a value of 68.8%, and 84.9%, while the conditions of building construction and public toilet sanitation facilities managed by the owner of a food stall. the respective values were 76%, and 91.7%.

Keywords: sanitary conditions, public toilets, tourist attractions, beach.